CERTIFICATE

Welding of railway vehicles and components according to EN 15085-2:2020

This is to certify that LASERSTAR Sp. z o.o. Sp. k.

Przy Lesie 4 87-100 Toruń Poland

is qualified to perform welding work within the range of certification of:

Classification level CL 1 and type of activity P – production according to EN 15085-2:2020

Field of application: Manufacturing of new assemblies and components for railway vehicles, except

design and except purchasing of welded parts.

Range of certification

Welding process according to EN ISO 4063	Material group according to ISO/TR 15608	Dimensions	Comments
135	1	t = 1,8÷30,0 mm	FW
		$t = 3.0 \div 20.0 \text{ mm}$	BW
	2	t = 3,0÷20,0 mm	BW
		$t = 3,0 \div 30,0 \text{ mm}$	FW
	8.1	$t = 2,1 \div 20,0 \text{ mm}$	FW
		$t = 3,0 \div 20,0 \text{ mm}$	BW
141	8.1	$t = 1,0\div 5,0 \text{ mm}$	BW
		$t = 1,5 \div 50,0 \text{ mm}$	FW
52	8.1	$t = 0.7 \div 2.0 \text{ mm}$	FW
23	8.1	t = 3,0	-

Responsible welding coordinator: Edyta Powęziak, (IWE) born: 25.05.1984

Deputy with equal rights: - born: -

Deputy: Waldemar Musiał, (Level C) born: 15.06.1993

 Comments:
 see reverse

 Certificate no.:
 TUVRh/15085/CL1/PL022/24

 Valid:
 from 09.09.2024 to 08.09.2027

Issued on: 09.09.2024

Auditor: Tomasz Jankowski

General regulations (see reverse)











www.tuv.com

Page 1 of 2

Certificate no.: TUVRh/15085/CL1/PL022/24

Comments:

Certification conditions EN 15085-2 are available on: www.tuv.pl/zalaczniki

The responsible welding coordinator Edyta Powęziak is authorized to test the qualification of welders according to the applicable standards within the range of certification of this Certificate.

General regulations

according to EN 15085-2:2020.

Revocation of the Certificate

Manufacturer certification body issuing this certificate may revoke the certificate if:

- there are justified doubts as to the proper execution of the welding work according to the stated standards,
- there are justified doubts as to the proper welding coordination according to the stated standards,
- no recognized welding coordinator is available any longer,
- no valid qualification test certificates for the welders and welding operators according to the specified standards are available,
- welders or welding operators without tested qualifications have been entrusted with the execution of welding work under the stated standards,
- other conditions according to the stated standards are no longer satisfied,
- the manufacturer certification body was refused an opportunity to perform the annual verification,
- the welding manufacturer waives the certificate.

The welding manufacturer shall acknowledge the revocation in writing to the manufacturer certification body. If a valid certificate is to be renewed, the renewal must be applied for with the manufacturer certification body at least two months before the end of the period of validity of the current certificate.

Distribution list:

- 1. Applicant (original)
- 2. Files